## Approved For Release 2002/10/25 : CIA-RDP72B00464R000400070094-2

OSA - 4142-66

ì	4	nc	T	<b>195</b> 6

SUBJECT: ECP GR-88 Rev. A, Contract CW 6744
Dear Chuck,
This ECP is technically approved by the SPO.  Request you provide with formal authority to STATINTL proceed with it.
should provide two Field Service Bulletins to implement this change - one for antenna controls and a second for antenna control testers. Also, should change the tester part number after modification.
We have been advised that ntends STATINTL to use a field team to modify antenna control testers which have been delivered.
Regards,

EdK

l Atch a/s

STATINTL

**STATINTL** 

**STATINTL** 

cy to: